Approved For Release 2002/10/29: CIA-RDP62B00844R000200070071-8

SAPC-19415 V Copy 2 of 4

MEMORANDUM FOR: Deputy Project Director

Il October 1957

SUBJECT

: Engine Problems

REFERENCE

: SAPC-20092

I agree with you that we should sometime this winter do a few tests along the lines suggested in paragraph 6 of reference to determine whether by leaving the ignition on during descent a quick and automatic relight would be ensured in the event of a flameout.

RICHARD M. BISSELL, JR. Project Director

RMB:djm 1-Addressee 2-Pro.Dir. Chrono 3-Pro. Dir FU 4-Pro. Chrono